

CAD Model Preparation:

The following is an overview for preparation of prospective CAD models to be used in the SIDE software.

Model units of measure: **Millimeters**

Model file extension: **STL ASCII**

Orientation of the model:

Place coordinate origin for both components at the center of glenosphere.

Assemble the implant components so that they are perfectly mated. Co-align the coordinate systems for the scapular and humeral components. Leave the poly insert within the assembled humeral stem for visualization purposes.

